




CGC STORIS PCB Clean Up





- PCB black foam pipe insulation was removed on 17 Jan 2007.
- The cutter was tied up at ISC Kodiak AK
- About 20 feet of insulation was removed.
- Two DC3's assisted me with the survey and removal.



CGC STORIS PCB Clean Up



CGC STORIS PCB Clean Up




CGC STORIS PCB Clean Up





Line on other side of bkhd, had different insulation on it.

CGC STORIS PCB Clean Up




Repair 2, thru bkhd, insulation removed


CGC STORIS PCB Clean Up




CGC STORIS PCB Clean Up





CGC STORIS PCB Clean Up



CGC STORIS PCB Clean Up




CGC STORIS PCB Clean Up




No picture showing the insulation removed.

CGC STORIS PCB Clean Up




CGC STORIS PCB Clean Up




- The project took about 4.5 hours to complete. This is from the start of the survey to delivering the PCB foam container to ISC Kodiak HazWaste TSDF.
- DC3 Skinner, DC3 Carter and myself went thru every compartment on board looking for the specific black foam pipe insulation that contained PCBs.

CGC STORIS PCB Clean Up




- As I had theorized, the PCB pipe insulation was installed as a patch job sometime in the past. The insulation was on the Potable Water lines.
- This project is representative of a project where PCB black foam insulation was used in a specific patch job.

CGC STORIS PCB Clean Up



- This project could not have been completed without the assistance of the following:
 - DC3 John Skinner, CGC STORIS, survey and removal
 - DC3 Coyet Carter, CGC STORIS, survey
 - Mr. Frederick “Fritz” Miller, HazWaste Bldg Operator, ISC Kodiak

CGC STORIS PCB Clean Up



Any questions, please contact:
Robert “Dennis” McMenamin,
Environmental Protection Specialist,
CG YARD, Safety Office